

Subject: JLG Safety Advisory

Importance: High



Advisory: Upper Lift Cylinder Pin Replacement on JLG Scissor Lifts

January 11, 2010

JLG Industries Inc. has issued a bulletin to advise JLG owners of a requirement to update the upper lift cylinder pin hardware on certain Model 2630ES, 2646ES, and 3246ES Scissor Lifts. Reports from the field have indicated that the upper lift cylinder pin retainer hardware could loosen over time, and, if overlooked during the required daily walk-around inspections, could allow the upper lift cylinder pin to disengage from the scissor arm stack. If this occurs, an elevated platform will drop to the fully lowered position. This update is to ensure that new upper lift cylinder pin retainer hardware is properly installed at this location. This bulletin must be completed on all affected units.

Affected machines include Model 2630ES, 2646ES, and 3246ES Scissor Lifts within the following serial number ranges:

Serial Numbers Affected*
0200112401 through 0200195024
1200001204 through 1200022235

**Reference the Master Serial Number Listing, available on JLG's Online Express, for individual serial numbers within this range.*

Further details on time for completion, required action, replacement parts/procedures, reimbursement and associated update forms are included in the bulletin.

The JLG bulletin can be found at:
[Advisory - Upper Lift Cylinder Pin Replacement on JLG Scissor Lifts](#) on JNet at Safety: Equipment and Tools: Heavy Equipment or Safety: Alerts and Advisories Index.